



Torq-Matic™ TM80 Tie Bar Crack

Issue

Canrig has been made aware of an instance where the Tie Bar for a TM80 has developed a crack. This may cause the overall wrench strength to weaken. The cause of the crack is under investigation. If necessary, Canrig will follow up with a bulletin with further recommendations. In the meantime, it is important for customers to visually inspect the Tie Bar along its entire length and where indicated below. If a crack is found, contact RigLine 24/7™ Support immediately.



Figure 1: Inspect the entire TM80 Tie Bar for cracks in the weld or material, especially the indicated area. Contact RigLine 24/7™ Support immediately if cracks are found.